

Exam Code: 920-443

Exam Name: nncse-succession 1000/1000m rls.3.0

Vendor: Nortel

Version: DEMO

Part: A

1: A multi-site Succession 1000/1000M RIs 3.0 system has just been networked to a third-party H.323 Gateway via IP Peer Networking. During call testing, it was discovered that NO Succession telephone calls can be completed to this third-party Gateway. Which three actions will determine the root cause or lead to the resolution of this call issue? (Choose three.)

- A. Verify the data network integrity to the third-party Gateway.
- B. Verify that the H.323 Signaling Gateways in both systems are running and registered with their appropriate H.323 Gatekeeper.
- C. Verify that the telephone(s) used for testing are compatible with this Gateway. If NOT, change to a H.323 compatible telephone.
- D. Verify that the H.323 Signaling Gateway application is installed and running on the Signaling Server in this system and in the third-party system.

ERROR: undefined
OFFENDING COMMAND: mFSF2S58YFFFFFFFA8

STACK:

[88.309 0 0 -88 0 0]
-dictionary-
/F2S58YFFFFFFFA8