

Vendor: Dell-EMC

Exam Code: D-PEMX-DY-23

Exam Name: Dell PowerEdge MX Modular Deploy 2023

Version: DEMO

QUESTION 1

What are two considerations when adding an MX760c in a chassis running OME-M firmware earlier than v2.0? (Select 2)

- A. If the MX760c is a thermally challenged system, the maximum supported ambient temperature cannot be reduced.
- B. If the MX760c is not a thermally challenged system, the sled is going to run as designed.
- C. All the fans on the PowerEdge MX7000 must be Silver Grade.
- D. If the iDRAC of the existing sleds is not at a supported level, ATMOS cannot calculate the maximum cooling.

Answer: AD

QUESTION 2

Which is a logical resource in SmartFabric?

- A. storage
- B. servers
- C. uplinks
- D. switches

Answer: C

QUESTION 3

What type of video connector is available for KVM connectivity on the PowerEdge MX7000 chassis?

- A. Mini-DVI
- B. DisplayPort
- C. VGA
- D. Mini DisplayPort

Answer: D

QUESTION 4

What is the maximum number of mezzanine cards that can be installed in an MX840c?

- A. 6
- B. 5
- C. 3
- D. 8

Answer: A

QUESTION 5

A PowerEdge MX7000 administrator is tasked to perform a chassis update using a catalog. Which source options are used to create the catalog?

 A. Newest validated stacks of chassis firmware on dell.com Latest component firmware versions on dell.com

Network path

B. Latest component firmware versions on dell.com Dell Update Package

Network path

- C. Newest validated stacks of chassis firmware on dell.com Dell Update Package Local Directory path
- Newest validated stacks of chassis firmware on dell.com Latest component firmware versions on dell.com
 Local Directory path

Answer: A

QUESTION 6

What is a function of the Fabric Resources Director (FReD)?

- A. SAS Expander routing for Fabric C
- B. Hosting OME-M interface
- C. Critical temperature monitoring
- D. Providing QuickSync 2 feature

Answer: C

QUESTION 7

An administrator is sending servers to other individuals but wants to reset the server to the factory default first.

What LifeCycle Controller feature is used to complete this action?

- A. Repurpose or Retire
- B. Set BIOS to defaults
- C. Delete RAID array
- D. RACADM RACRESETCFG

Answer: A

QUESTION 8

What is the connection protocol between FReD and MM?

- A. HDMI
- B. Ethernet
- C. I2C
- D. FC

Answer: C

QUESTION 9

Which two actions are possible using the Chassis Deployment Wizard? (Select 2)

- A. The LCD pin can be configured.
- B. The administrator can use an existing chassis profile to configure the chassis.
- C. The firmware catalog can be configured using the FTP protocol.
- D. The network I/O Module password can be configured.

Answer: BC

QUESTION 10

A customer wants to change the switch operating mode from SmartFabric mode to Full Switch mode. After deleting the fabric in OME-M, what configuration is retained on the switch?

- A. admin password, hostname, management IP Address, and the VLT domain configuration
- B. admin password, hostname, and management IP Address
- C. admin password, hostname, management IP Address, and all port breakout configuration
- D. admin password, hostname, management IP Address, and the VLAN database

Answer: B

QUESTION 11

What is the minimum OME-M version required to use ATMOS?

- A. 1.40.00
- B. 2.00.00
- C. 2.10.00
- D. 1.60.50

Answer: B

QUESTION 12

Which command(s) is supported in the current PowerEdge MX Redfish implementation?

- A. PUT and DELETE
- B. PUT only
- C. HEAD and PUT
- D. GET and DELETE

Answer: D

QUESTION 13

After a main board replacement, the easy restore process was not successful. A system administrator is not able to launch the Virtual Console.

What is the cause of this issue?

- A. ActiveX is not installed.
- B. Java is not installed.
- C. Enterprise license is not installed.
- D. KVM is not present.

Answer: C

QUESTION 14

A customer would like to periodically change the iDRAC root password on all the servers in their MCM Group.

What feature in OME-M should they use?

- A. SupportAssist
- B. Resource Pools
- C. Quick Deploy
- D. Chassis Deployment Wizard

Answer: C

QUESTION 15

What is the port configuration of an MX5108n switch?

- A. 16 x internal 25GbE ports
 - 4 x 40GbE QSFP+ ports
 - 2 x 100GbE QSFP28 ports
 - 1 x 10GbE RJ45 Base-T port
- B. 8 x internal 25GbE ports
 - 1 x 40GbE QSFP+ port
 - 2 x 100GbE QSFP28 ports
 - 4 x 10GbE RJ45 Base-T ports
- C. 8 x internal 25GbE ports
 - 2 x 40GbE QSFP+ ports
 - 1 x 100GbE QSFP28 port
 - 4 x 10GbE RJ45 Base-T ports
- D. 16 x internal 25GbE ports
 - 1 x 40GbE QSFP+ port
 - 2 x 100GbE QSFP28 ports
 - 4 x 10GbE RJ45 Base-T ports

Answer: B

QUESTION 16

What item is used to refer to a daisy-chained configuration of a multiple MX7000 chassis environment?

- A. Wired group
- B. Identity group
- C. Chassis group
- D. Physical group

Answer: A

Thank You for Trying Our Product

Passleader Certification Exam Features:

- ★ More than 99,900 Satisfied Customers Worldwide.
- ★ Average 99.9% Success Rate.
- ★ Free Update to match latest and real exam scenarios.
- ★ Instant Download Access! No Setup required.
- ★ Questions & Answers are downloadable in PDF format and VCE test engine format.





- ★ Multi-Platform capabilities Windows, Laptop, Mac, Android, iPhone, iPod, iPad.
- ★ 100% Guaranteed Success or 100% Money Back Guarantee.
- ★ Fast, helpful support 24x7.

View list of all certification exams: http://www.passleader.com/all-products.html

























10% Discount Coupon Code: ASTR14